

Tools & Resources

Bug Search Tool

[Bug Search](#) CSCvr62983

[Help](#) | [Feedback](#)

Bug CSCvr62983 is a duplicate of the bug displayed below

AP reporting its own MAC as rogue

CSCvr62983

Description

Symptom:

The AP may report its own MAC as rogue.

Relevant outputs for IOS-XE base WLC -
show ap summary (to check managed AP Radio MAC)
show wireless wps rogue ap ssid summary (to check for MAC Addresses in the same range as the Radio MAC in the output above)
show wireless wps rogue ap detailed (use the MAC address from the second output above)

Conditions:

Not known

Workaround:

Not known at this time.

Further Problem Description:

Was the description about this Bug Helpful? (0)

Details

Last Modified: Dec 18, 2020

Known Affected Releases: (1)

Known Fixed Releases: (0)

Status: Other

ap-17.2.0.16

[Download software for Cisco Aironet 1850 Series Access Points](#)

Severity: 2 Severe

Product: (1)

Cisco Aironet 1850 Series Access Points

Support Cases: 5

Customer Visible

- [Notifications](#)
- [Save Bug](#)
- [Open Support Case](#)